TEST REPORT

No. : GZIN2507001360CM03_EN

Date : 2025-08-01

Scan to see the report

GZIN2507001360CM03

Verification: check.sgsonline.com.cn

CUSTOMER NAME: VIEW FAST (HK)LIMITED

ADDRESS: FLAT 1008, 10/F SHUN FAT INDUSTRIAL BUILDING, 17 WANG HOI ROAD, KOWLOON BAY, HK

Sample Name	:	High-Strength Self-Leveling Cement
Manufacturer	:	Foshan Kaiju Technology Co., Ltd.
Buyer	:	VIEW FAST (HK)LIMITED
Other Information	:	Brand：TIMANTI

Above information and sample(s) was/were submitted and confirmed by the client. SGS, however, assumes no responsibility to verify the accuracy, adequacy and completeness of the sample information provided by client.

****

SGS Ref. No.	:	NBIN2507002247PL03
Date of Receipt	:	2025-07-24
Testing Period	:	2025-07-24 ~ 2025-08-01
Test result(s)	:	For further details, please refer to the following page(s) (Unless otherwise stated the results shown in this test report refer only to the sample(s) tested)

Signed for
SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch.

Tobby Yang
Authorized signatory

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.

Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国・广东・广州市黄埔区开创大道1501号3栋101房 邮编：510760

t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT

No. : GZIN2507001360CM03_EN


Date : 2025-08-01

Summary of Results:

No.	Test Item	Test Method	Result	Conclusion
1	Slip resistance	BS 8204-3:2004+A2:2011 Section 6.15 and BS 7976-2:2002+A1:2013	See result	Pass
2	Slip resistance	BS 8204-4:2004 Section 8.4 and BS 7976-2:2002+A1:2013	See result	Pass

Note: Pass : Meet the requirements;
Fail : Does not meet the requirements;
N/A : Not Apply to the judgment.

Original Sample Photo:



Sample

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Comprehensive Testing Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国·广东·广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com
Member of the SGS Group (SGS SA)

TEST REPORT

Test Item 1: Slip resistance

Sample description: see photo

Test Method: BS 8204-3:2004+A2:2011 Section 6.15 and BS 7976-2:2002+A1:2013

Test Condition:

Specimens: 250mm×150mm×12.05mm

Type of slider: slider 55 (TRL rubber)

Lab Environmental Condition: 21.0℃

Testing surface: see photo

Test Result:

Test item	Result	Requirement in BS 8204-3:2004+A2:2011 Section 6.15	Conclusion
Pendulum test value (dry surface)	60	≥40	Pass
Pendulum test value (wet surface)	50		

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Commercial Inspection Testing Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国・广东・广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com

Member of the SGS Group (SGS SA)

TEST REPORT

Test Item 2: Slip resistance

Sample description: see photo

Test Method: BS 8204-4:2004 Section 8.4 and BS 7976-2:2002+A1:2013

Test Condition:

Specimens: 250mm×150mm×12.05mm

Type of slider: slider 55 (TRL rubber)

Lab Environmental Condition: 21.0℃

Testing surface: see photo

Test Result:

Test item	Result	Requirement in BS 8204-4:2004 Section 8.4	Conclusion
Pendulum test value (dry surface)	60	≥40	Pass
Pendulum test value (wet surface)	48		

Appendix information:

1. The test report shall only be used for clients' scientific research, teaching, internal quality control, product research and development, etc., and just for internal reference.
2. Unless otherwise stated, this report provides a declaration of conformity according to whether the test results are within the specified limits or specifications without considering the measurement uncertainty.

********End of report********

SGS-CSTC Standards Technical Services Co., Ltd. Guangzhou Branch Comprehensive Technical Services Laboratory
检验检测专用章 Inspection & Testing Services

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 30 days only.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com
Room 101, Building 3, No.1501, Kaichuang Avenue, Huangpu District, Guangzhou, Guangdong Province, China 510760
中国・广东・广州市黄埔区开创大道1501号3栋101房 邮编：510760
t (86-20) 82155688 www.sgsgroup.com.cn
t (86-20) 82155688 sgs.china@sgs.com
Member of the SGS Group (SGS SA)